

<<HSE警示录>>

图书基本信息

书名：<<HSE警示录>>

13位ISBN编号：9787502183486

10位ISBN编号：7502183485

出版时间：2011-3

出版时间：石油工业出版社

作者：中国石油海外勘探开发公司 编

页数：244

版权说明：本站所提供下载的PDF图书仅提供预览和简介，请支持正版图书。

更多资源请访问：<http://www.tushu007.com>

<<HSE警示录>>

内容概要

继2010年7月印发《HSE警示录》之后，又推出了《HSE警示录(二)》。书中的47起事故事件就发生在近两年，发生在我们身边。事故的当事人、受害人有的是我们的同事、朋友，有的是为我们提供服务的承包商、分包商员工。一次小小的疏忽、一个简单的错误、一个不安全的行为，就可能酿成一起事故，造成无法挽回的人身伤亡或重大财产损失，毁掉个人的生命、家庭的幸福、企业的安定、社会的和谐。教训之深刻，后果之惨重，令我们痛心，更令我们反思。

<<HSE警示录>>

书籍目录

Group 1 Caught In, Under or Between
Worker Caught Between Truck and Skid Pump
Foreman Pressed by Heavy Electrical Cabinet
Pipe Yard Worker Suffered Thumb Injury
Fingers Crushed by Roller
Hand Pinched during Assembling Work
Group 2 Cut, Puncture, Scrape
Finger Joint Lost When Shutting off Wood Cutting
Machine
Group 3 Explosions or Burns
Vacuum Truck Explosion
Inflammation during Tanker Loading
Refrigerator Truck Explosion
Burn by Fire from Gas Leakage
Automotive Technician Injured in Tire Explosion
Driver Injured by Tyre Rupture
Battery Explosion
Operator Burnt by Steam
Burn by Hot Formation Water
Group 4 Exposure: Electrocutation
Worker Killed by Overhead Power Line
Group 5 Exposure: Noise, Pressure, Chemical,
Biological, Vibration
Bulldozer Operator Attacked by Wasps
Escape from H₂S Poisoning
Bathroom Cleaner Suffered Eye Injury
Group 6 Falls From Height
Assistant Welder Fell From Height
Security Guard Fell into a Cellar
Group 7 Overexertion/Strain
Back Injured When Lifting Boxes
Group 8 Slips and Trips(at the same height)
Burn after Slip in Kitchen
Group 9 Struck By
Driller Assistant Hit by Pipe Wrench
Hand Injury during Casing Running
Construction Worker Hit by Tent Frame
Operator Struck by Broken Knuckle Joint
Leg Injured by Swinging Pipe
Welder Injured By Plate Falling from Drill Floor
Group 10 Vehicle Crashes
Fatal Traffic Accident at Field Bypass Road
Collision Between a Dump Truck and a Fuel Tanker
Fatal Traffic Accident Due to Overspeeding
Worker Killed When Sheltering under Truck

<<HSE警示录>>

Security Patrolling Vehicle Accident
Rollover Accident during Rig Move
Group 11 Non-injurious Accident
Exploratory Well Blowout during Production
Testing
Pipeline Leakage
Oil Spilled from Vent Pond
Pollution Resulted from Oil Well Blow-out
Explosion of Buffer Tank in Metering Station
Fire from Tanker Welding
Fire Incident from Welding Operation
Meeting Room Fire
Scrap Yard Fire
Bakery Container Fire
Fiber Optical Cable Damaged by Excavator
Group 12 Near Miss
Excavation Near Miss Due to Non-compliance

<<HSE警示录>>

版权说明

本站所提供下载的PDF图书仅提供预览和简介，请支持正版图书。

更多资源请访问:<http://www.tushu007.com>